

Tarifa de recambios

2014

Código Completo	Grupo PVP	PVP 2014 (€)
30668	RE4	200,00
42452	RA9	2,30
83094	RB9	41,40
84499	RC6	41,40
101394	RF9	85,90
4392K-00	RC6	30,90
4393K-00	RC6	48,40
4755-CP-WC	RD8	175,10
4770K-00	RC8	44,30
6472K-00	RC9	59,70
8094K-00	RC8	48,40
8319K-00	RC8	57,80
8320K-00	RD2	92,40
8407K-00	RC6	42,20
8409K-00	RD1	84,50
C23075010	RD4	122,21
E10158-NF	RB8	5,90
E1052-00	RC2	18,50
E1088-00	RC5	44,40
E1134-00	RC5	57,60
E1361-00	RC5	78,80
E1416-00	RE6	289,90
E1470-5M	RD1	72,10
E1598-00	RC6	51,50
E1678-00	RC2	20,00
E1811-00	RC6	59,60
E1982	RA1	1,31
E1992-00	RB9	11,10
E2596-NF	RC8	50,50
E3009-00	RB6	3,64
E3010-00	RA4	3,64
E3019-CP	RB1	2,02
E3048-CP	RB9	5,05
E3062-00	RB3	3,64
E3070-CP	RC4	25,25
E3072-CP	RC4	32,32
E3074-CP	RC7	60,60
E3078-CP	RB9	28,28
E3081-NF	RA5	1,00
E3082-NF	RC2	13,10
E3086-50	RB9	11,21
E3087-00	RB3	9,60
E3088-00	RA9	3,80
E3090-00	RD6	140,39
E3091-CP	RC3	33,33
E3092-00	RB9	20,00

Código Completo	Grupo PVP	PVP 2014 (€)
E3095-00	RE1	220,18
E3097-00	RC1	13,74
E3099-CP	RC1	19,50
E3105-00	RB1	3,64
E31060-00	RB7	13,64
E3107-00	RB1	3,64
E3113-00	RB3	3,64
E3117-CP	RD3	92,70
E3118-00	RC1	12,22
E3131-CP	RC5	34,00
E3133-CP	RC5	32,32
E3231-NF	RC1	18,50
E3335-CP	RA8	2,02
E4061-CP	RA9	3,60
E4063-CP	RB3	21,21
E4113-NF	RC4	18,50
E4206-00	RC2	18,50
E4246-CP	RB2	5,10
E4257-00	RC6	35,00
E4286-CP	RC3	35,00
E4303-00	RC6	36,10
E4310-NF	RC6	39,39
E4314-NF	RD1	54,50
E4317-NF	RC1	12,90
E4352-00	RB8	12,30
E4357G-00	RC4	20,60
E4384-00	RC2	11,50
E4386-00	RD4	66,70
E4516-NF	RD2	56,70
E4535-NF	RB1	8,10
E4545-NF	RA9	2,02
E4550	RB2	6,26
E4598-NF	RB7	10,10
E4715-00	RC2	18,50
E4744-00	RC9	50,00
E4750-00	RC6	49,40
E4752-CP	RC3	13,43
E4787-00	RB9	21,90
E4818-00	RC7	65,70
E4835-00	RC2	13,00
E4900-00	RD5	150,00
E5510-NF	RB5	7,47
E5511-NF	RC4	21,21
E5514-NF	RC9	82,82
E5534-CP	RC4	32,32
E5539-00	RB2	8,70

Código Completo	Grupo PVP	PVP 2014 (€)
E5548-00	RB6	13,43
E5555-CP	RC4	25,25
E5559-00	RB6	12,22
E5569-CP	RC5	32,32
E5576-CP	RC3	27,30
E5577-NF	RB9	25,25
E6019-00	RC7	42,20
E6030-00	RC1	12,22
E6036-00	RC7	42,20
E6046-00	RD2	84,50
E6050-CP	RC3	24,20
E6095-NF	RC4	16,20
E6242-CP	RB9	16,20
E62487-00	RE7	335,00
E6249-CP	RC1	12,30
E6275-NF	RC3	9,10
E6276-NF	RC3	9,10
E6331-NF	RC6	29,30
E6349-CP	RC5	46,30
E6360-00	RC6	48,40
E6362-00	RC8	85,50
E6369-00	RD9	178,20
E6371-00	RD8	185,40
E6374-00	RD9	102,00
E6376-00	RD9	102,00
E6377-00	RD5	91,70
E6384-CP	RC3	35,00
E6387-50	RC9	87,60
E6388-00	RC6	46,40
E6390-00	RC7	83,40
E6392-00	RF3	497,50
E6398-00	RD9	113,30
E6402-00	RD1	67,00
E6410-00	RD9	170,00
E6420-00	RD3	86,86
E6432-50	RC6	85,50
E6436-CP	RC4	20,30
E6442-CP	RC3	20,20
E6452-NF	RB2	5,10
E6467	RC3	27,27
E6469-CP	RB2	3,64
E6469-CP	RB2	3,64
E6487	RB5	3,64
E6487	RB5	3,64
E6501-00	RC8	72,10
E6508-CP	RB2	5,05

Jacob Delafon España, S.A.

Ctra. de Logroño, km. 17
50629 Sobradriel - Zaragoza

Teléfono atención al cliente: 902 46 46 86
Teléfono asistencia técnica: 902 11 38 36

www.jacobdelafon.es

Jacob Delafon
PARIS

Código Completo	Grupo PVP	PVP 2014 (€)
E6513-CP	RA5	1,31
E6574-00	RC6	108,20
E6580-NF	RB7	17,90
E6595-00	RD9	144,20
E6602-NF	RD6	152,50
E6609-00	RE2	197,80
E6673-NF	RB6	5,10
E6693-NF	RB8	7,60
E6704-CP	RC7	70,70
E6705-CP	RC9	96,96
E6752-CP	RC7	41,00
E6767	RA1	1,31
E6778-CP	RD1	73,73
E6779-CP	RB5	7,27
E6788-CP	RB2	6,26
E6791-CP	RB2	5,05
E6902-CP	RB5	12,22
E6909-5U	RB6	9,70
E6917-CP	RA6	3,64
E70002-00	RC9	65,90
E70004-00	RD1	89,60
E70004-00	RD1	89,60
E70005-00	RC9	63,90
E70006-00	RC9	61,80
E70007-00	RD1	59,70
E70007-00	RD1	59,70
E70008-00	RC8	67,00
E70009-00	RC7	42,20
E70011-00	RD1	84,50
E70016-00	RD2	68,00
E70017-00	RC6	38,10
E70019-00	RD5	150,00
E72200-CP	RC7	36,40
E72281-CP	RD1	76,80
E73091-NF	RC8	41,40
E73093-01R	RC2	11,10
E73093-CP	RC2	32,30
E74138-CP	RC5	29,30
E74182-CP	RD9	123,20
E74183-CP	RD4	74,70
E74184-CP	RD3	70,70
E74188-CP	RD1	77,80
E74193-NF	RD1	86,90
E74197-CP	RC3	24,20
E74203-NF	RC4	22,22
E74207-NF	RF7	595,90
E74526-CP	RC9	51,50
E74527-CP	RC6	38,40
E74551-CP	RA5	110,10
E74560-CP	RC3	29,30
E75112-CP	RC8	132,90
E75114-CP	RC8	77,30

Código Completo	Grupo PVP	PVP 2014 (€)
E75513-NF	RC4	20,30
E75535-CP	RA9	3,50
E75546-CP	RD7	100,00
E75573-NF	RB3	13,30
E78000-CP	RC3	20,20
E78160G-CP	RC6	29,30
E78161-CP	RC4	41,40
E78168-CP	RC5	32,00
E78170-CP	RB9	9,30
E78212-CP	RC6	31,30
E78261-00	RC5	34,30
E78286-ZZ-CP	RC6	34,30
E78287-CP	RC6	30,30
E78290-CP	RC3	13,10
E78291-CP	RD3	85,90
E78294-NF	RD2	95,95
E78294-NF	RD2	95,95
E78295-NF	RD2	95,95
E78296-CP	RC6	37,40
E78297-CP	RC9	56,60
E78300-CP	RC1	18,89
E78301-CP	RB7	18,89
E78302-CP	RC2	21,21
E78303-CP	RC1	18,89
E78315-CP	RC4	47,50
E78548-CP	RC8	59,60
E78561-CP	RB9	9,10
E78585-CP	RC5	34,30
E8500	RA6	2,42
E8501	RA3	1,31
E8508-CP	RB1	3,64
E8915-CP	RC6	29,30
E9203	RC5	36,36
E9605-5J	RC6	25,80
E98700-CP	RC3	30,00
E98710-CP	RD6	115,00
ETA008-CP	RD1	52,50
ETA011-CP	RC4	25,80
ETA017-CP	RD1	92,40
ETA018-CP	RC8	103,00
ETA019-01R	RB3	9,90
ETA020-01R	RC1	17,40
ETA024-CP	RC6	54,60
ETA025-CP	RC6	50,50
ETA026-00	RC1	9,60
ETA027-CP	RB6	11,90
ETA028-CP	RC6	50,50
ETA029-00	RA8	3,10
ETA044-CP	RB9	9,30
ETA045-00	RA9	10,20
ETA051-CP	RC1	15,50
ETA053-CP	RC6	54,54

Código Completo	Grupo PVP	PVP 2014 (€)
ETA054-CP	RC4	23,20
ETA055-CP	RC5	23,10
ETA067-CP	RC6	31,50
ETA068-CP	RC2	13,80
ETA073-CP	RA9	5,80
ETA075-CP	RC7	49,40
ETA094-00	RA6	3,00
ETA095-CP	RC2	15,00
ETA104-CP	RC3	15,00
ETA105-CP	RC3	15,00
ETA139-CP	RC3	15,00
EWA161-CP	RC1	21,21
EWA162-CP	RB7	13,43
EWA163-CP	RC6	51,51
R100125NF	RC5	19,19
R100502NF	RC3	21,21
R26606070	RC2	21,20
R29304624	RB6	11,00
R29304818	RB6	10,00
R29305328	RC3	19,50
RPA051NF	RC1	17,00
RPA111NF	RC1	12,30
RPA122NF	RB7	18,20
RPA224NF	RB9	15,50
RPA333NF	RC5	20,20
RPA334NF	RC3	20,20
RPA336NF	RC3	20,20
RPA371NF	RC1	16,20
RTA013NF	RC2	21,21
RTA016NF	RC2	21,20
RTA022NF	RB9	13,30
RTA034NF	RC3	22,00
RTA050NF	RB9	19,60
RTA052NF	RC3	18,40
RTA058NF	RC3	16,20
RTA059NF	RC3	16,20
RTA060NF	RC3	15,00
RTA061NF	RC3	15,00
RTA062NF	RB7	6,10
RTA063NF	RC7	37,80
RTA066NF	RC5	22,20
RTA074NF	RC3	22,00
RTA076NF	RC1	11,50
RTA077NF	RC1	14,14
RTA078NF	RC4	21,20
RTA084NF	RC5	27,27
RTA096NF	RC4	25,00
RTA097NF	RC5	30,00
RWA206NF	RC8	56,00
RWA207NF	RC8	121,00
RWA229NF	RB1	4,10
RWA562NF	RC7	40,00